

3 Axis (X, Y, Z) Stepping Motor Controller (Rev 3.0 Dec09)

Presents by

Marco K. Wong

Annex Depot Inc Copy Rights 2009


This is a 3 Axis (X,Y,Z) CNC stepping motor controller/Driver. It built-in a spindle relay and all input is optical isolated from the outside providing safe (no feedback to your PC) and better response time. Support Mach2, Mach3, ArtCam, KCam. You can apply this card to a CNC machine or upgrade your old CNC machine to take advantage of new technology. It works for CO2 laser machine as well

Features:

- * Optical isolation for data In/Out
- * Relay control for spindle (or laser)
- * Four step speed setting
- * High current Output
- * Big Heat sink support up to 2.5A

Specification:

- * In/Out Interface port: Parallel
- * Built in Relay control for spindle
- * Support 2/4 phases 4, 6, 8 wires stepping motor
- * High speed optical isolation coupling
- * Built in No. 4 Axis interface for expansion
- * LED indicators for each Axis & Relay
- * Current: 2A (2.5A max)
- * Resolution: 1/8, 1/4, 1/2, 1
- * Power: Single DC 12 ~ 24V (no 5V needed)
- * Control port: DB manual control interface
- * CAD system support: March2, Mach3, ArtCam, KCam




ColdfusionX
Annex Depot Lightobject.com




ColdfusionX
Annex Depot Inc
www.lightobject.com

DB 25 Connector Pin layout




PIN1	PIN2	PIN3	PIN3	PIN5	PIN6	PIN7	PIN8	PIN9	PIN10
CKE	CKA	CWA	CKB	CWB	CKC	CWC			DIN1
E STEP	A STEP	A DIR	B STEP	B DIR	C STEP	C DIR			Limit1
PIN11	PIN12	PIN13	PIN14	PIN16	PIN17	PIN18-25			
DIN2	DIN3	DIN4	CWE	EN	RLY	GND			
Limit2	Limit3	Limit4	E DIR	Enable	Relay	Ground			






DB 15 Connector Pin layout




P1	P2	P3	P4	P5	P6	P7	P8	P9	P10	P11	P12	P13	P14	P15
CKA	CWA	CKB	CWB	CKC	CWC			CKE	CWE	EN	MOT	VCC		GND
A STEP	A DIR	B STEP	B DIR	C STEP	C DIR			E STEP	E DIR	En-able	Motor	Pwr		Gnd




2 phases,4 phases stepping motor connection diagram (current 2A max)






Power

The controller can take DC 12~32V power input. The power supply should be able to provide at least 3A current in order to support smooth operation.




Home Limit and Emergency Stop Input pin

Note: All Limit Input are Active Low *




4th Axis Expansion Output pin

CW = PIN #14. It's used to output PWM signal as well. Or, you can use the output from #14 to trigger a 'Fire' signal for CO2 laser. The output level is +5 pulse so the CO2 power supply must support +5V triggering!




Resolution/ Speed Setting for X,Y,Z Stepping Motor




Full STEP	1/2 STEP	1/4 STEP	1/8 STEP
1 - Off	1 – Off	1 - On	1 - On
2 - Off	2 - On	2 - Off	2 - On

Note: Signal Ground and the Output ground are totally isolated, no physical connection. But all grounds from the optical isolation module share the same ground.





CO2 laser engraving machine 'Firing' setup


CW – the direction output of Z stepping motor send +5V when Z value change in positive direction (user configuration). It's connected to the COM port of the relay and the GND is connected to the Gnd(ground) of the CO2 power supply. Note, the power supply must support 5V triggering as the 'CW' output signal is TTL level, either in 0V or in 5V.





MACH3 Setup. Note: some parameters is in default setting




















Please go to Mach3 website <http://www.machsupport.com/> to get more update information. We don't support Mach3 or other 3rd software.

www.LightObject.com