



## DSP Adding Analog Output Procedures



Lightobject.com

**Parts list:**

IC: 2x **TLP521-2**



1x **MC33202P**




VR: 2x **10K3266**



**Parts installation:**

- 1) On U45 position, add a TLP521-2 IC
- 2) On U31 position, add a TLP521-2 IC
- 3) On U32 position, add a MC33202P IC
- 4) On VR0 position, add a 10K3266 VR
- 5) On VR1 position, add a 10K3266 VR



### Des-soldering:

Jumper JP4 and JP5 has been soldered so it need to break it out to enable selection of Analog or PWM output

